Tarantin REPAIR KITS - Multivalves, Filler & Vapor Valves Quick Reference Guide For Repair Kits

Make sure you are thoroughly trained before you attempt any valve repair or maintenance. Improper conditions or procedures can cause accidents resulting in property damage and personal injury.

	Μ	ultivalv	es - Fi	iller Valve 3			
Part Numbe	Kit Number		Kit Contents				
6532 Series 6533 Series 6542 Series 6543 Series		6542E w/uppe		Gaskets; spring; spring guide; stem and seat disc assembly; upper body			
(Mfd. Oct. 19 or before)	8555 Series *(Mfd. Oct. 1990 or before) 8555DL Series		3-80 er body	Gaskets; spring; spring guide; stem and seat disc assembly			
6555 Series 8555 Series* *(Mfd. after Oct. 1990) G8475 Series 8596AR16.0		8555-50 w/ upper body		Gaskets; spring; spring guide; stem and seat disc assembly; upper body			
		8555-80 w/o upper body		Gaskets; spring; spring guide; stem and seat disc assembly			
		8475-50 w/ upper body		Gaskets; seat disc & retainer assembly; spring; upper body			
		8475-80 w/o upper body		Gaskets; seat disc & retainer assembly; spring			
		Fille	er Valv	/es			
Part Number				Kit Contents			
7547 Series (Obsolete) 75		47B-80	Gaskets; spring; seat disc & retainer assembly				
6579	7579-50 w/ upper body		Gaskets; seat disc & retainer assembly; spring; upper body				
7579	7579-80 w/o upper body		Gaskets; seat disc & retainer assembly; spring				
7647 Series	76	47B-80	Gaskets; spring; seat disc & retainer assembly				
Seal cap made of tough, resilient molded plastic. Protects threads and internal working parts. Caps are designed to contain normal tank pressures, and must be kept on valves at all times.							

and must be k valves at all times.

Long-wearing gasket permits handtight connection of cap and hose



Safety groove is designed to shear below the ACME thread, leaving the valve seats closed and unaffected if the delivery truck pulls away with the hose connected.

Seat disc of special synthetic composition is extra thick for longer life.

Valve guide is precision machined to assure positive seal

Exclusive swing-away lower back check valve for extra fast filling is provided on Models 6579 and 6587. Differs from conventional design by swiveling to a vertical position when opened.



plastic. Protects threads and internal working parts. Caps are designed to contain normal tank pressures, and must be kept on valves at all times. Long-wearing gasket permits hand-tight connection of cap and hose coupling. Seat disc of special synthetic composition is extra thick for longer life.

Valve guide is precision machined to assure positive seal.

100	Vapor Return Valves								
Mo.	Part Number Kit Number		Kit Contents						
	7573A	7573A-81	Gaskets; spring; seat disc & retainer						




1 Multivalves - Vapor Equalizing							
Part Number	Kit Number	Kit Contents					
7556V Series G8475 Series	8475-51A	Body; gaskets; spring; stem and seat disc assembly					
8593AR16.0	8555-80 w/o upper body	Gaskets; spring; stem and seat disc assembly					
2 Multivalves - Service Valves							
Part Number	Kit Number	Kit Contents					
6532A Series, 6533A Series, 6542A Series,	19100-50B	Bonnet; stem and o-ring assembly; handwheel; self-tapping screw					
6543A Series, 6555D Series, 7556V Series, 8555D Series, 8555DL Series	19104-50	Complete MultiBonnet assembly-bonnet assembly; handwheel; nameplate;					
6532R Series, 6533R Series,		selftapping screw					
6542R Series, 6553R Series, 6555R Series, 7556R Series, 68475R Series, 8555R Series, 8593AR16.0 Series, 9101R Series	19104-80	Upper packing with seal rings - For MultiBonnet only					

Multivalves									
Multivalve		Container	Repair Kits						
Part No.	Replaced by	Connection	Service Valve	Filler Valve	Vapor Equalizing				
1470LV, 1480V, 1470W, 1480W	G8475RV, G8475RW	2-1/2"M.	3100-80A,bonnet-diaphragm-stem 3100-80B, diaphragm, washer 3100-81K,conversion,bonnet assy	1475-80, kit	2418-51, assy				
2180	8555 for 200# Cyl, 6543 for 420# Cyl	3/4"	no repair parts available replace due to age						
2418	G8475RV	2-1/2"F.	7128-5,diaphragm assy	n/a	2418-51, assy				
2465, 2486	G8475RV	2-1/2"F.	7128-5,diaphragm assy	n/a					
2550	G8475RV	2-1/2"M	7128-5,diaphragm assy	n/a	2418-51, assy				
2555 Series	6532, 6533, 6542, 6543	3/4", 1"	replace due to age						
2557 Series	no replacement	1-1/2"	no repair parts available						
2577	6532, 6533, 6542, 6543	3/4", 1"	no repair parts available replace due to age						
2580, 2581	8555D/8555R	3/4"	no repair parts available						
2593, 2594	8593AL16.0	1-1/2"	3100-80A,bonnet-diaphragm-stem 3100-80B,diaphragm,washer 3100-81K,conversion,bonnet assy	1475-80, kit	2418-51, assy				
2418-51,assy	8593AR16.0 not a direct replacement	1-1/2"	3100-80A,bonnet-diaphragm-stem 3100-80B,diaphragm,washer 3100-81K,conversion,bonnet assy	1475-80, kit	2418-51, assy				
6477A	n/a	2-1/2"M.	8100-50,bonnet assy,handwheel	8475-50,-80	8475-51A, kit				
6533D, 6542D, 6543D		3/4", 1"	903-50 (lg), 903-51 (sm),kits	6542-50,-80					
7555	8555D/R	3/4"	replace due to age						
7556, mfg before 1962		3/4"	8100-50, bonnet assy, hand wheel						
G8475, mfg before 1962		2-1/2"F.	8100-50,bonnet assy,handwheel	8475-50,-80	8475-51A, kit				
8477, mfg before 1962	G8475RV	2-1/2"F.	8100-50, bonnet assy, hand wheel	8475-50,-80	8475-51A, kit				
8484, mfg before 1962	no replacement*		8100-50,bonnet assy,handwheel		8475-51A, kit				
8484A	no replacement*		19100-50B/19104-50,kit		8475-51A,kit				
8555, mfg before 1962	8555D/R		no repair parts available replace due to age						
8555S			903-50 (lg), 903-51 (sm),kits	6542B-50,-80					
8593K, 8594K, mfg before 1962	8593AR16.0		8100-50,bonnet assy,handwheel	8475-50,-80	8475-51A, kit				
8594	8593AR16.0		8100-50,bonnet assy,handwheel						
8594/K, mfg after 1962	8593AR16.0		19100-50B/19104-50,kit	8475-50,-80	8475-51A,kit				
*Tanks equiped with obsolete 8484 & 8484A series valve can be retained in service. Please call your Tarantin for information.									

800-922-0724 • www.tarantin.com

Tarantin REPAIR KITS - Multivalves, Filler & Vapor Valves NDUSTRIES, INC. Quick Reference Guide For REGO Repair Kits

Make sure you are thoroughly trained before you attempt any valve repair or maintenance. Improper conditions or procedures can cause accidents resulting in property damage and personal injury.



903-50

7128-5

Bonnet

Dia. Assy

9

10

Reg0 900 Series

Old style 2400 & 2500